

BRINKLEY

Awning Bolt Replacement

CSC-2301

Notification Date 2-8-23

Issue:

BRV has issued a Customer Satisfaction Campaign (CSC-2301) regarding the LCI Awning Pitch Bolt. There is a concern that these can shear in operation rendering the pitch adjustment inoperable.

Action:

Remove and replace the pitch bolt on all Awning assemblies on the coach (4 bolts in total).

Labor Allowance: .25 hr. each (.5 total for both awnings).

Flat Rate Code: CSC-2301

Parts Needed: (BRV Supplied)

4 Pitch Bolts with nuts and washers

****Please reference the LCI instructional link that coincide with this document****

https://lci-support-doc.s3.amazonaws.com/technical-information-sheets/awnings/ccd_0002218.pdf