

BRINKLEY

Attic Vent Replacement

CSC-2304

Notification Date 2-8-23

Issue:

BRV has issued a Customer Satisfaction Campaign (CSC-2304) regarding the Attic vents on the roof assembly. The affected units in this vin range had a primer applied to the attic vent itself that could cause the material to prematurely crack allowing water infiltration into the roofing assembly.

Action:

Remove and Replace ALL attic vents on roofing assembly with BRV supplied parts and sealants.

Labor Allowance: .3 hr. each

Flat Rate Code: CSC-2304

Parts Needed: (BRV Supplied)

3 Attic Vents

5 ft. of BRV approved Butyl tape to prep vent(s).

AlphaThane Roof Sealant to topcoat vent attachments.

